$$SFR = Q/1000$$

where

SFR = steam flow rate (lb/hr)

Q = heat flow (Btuh)

1000 = heat (Btu) liberated by condensation

of 1 lb of steam